



AREA TO BE REPAIRED

POLYGUARD UNDERSLAB MEMBRANE FABRIC PREPARED WITH POLYGUARD 650 LT LIQUID ADHESIVE OR POLYGUARD CALIFORNIA SEALANT APPLIED TO A CLEANED AREA 6" BEYOND THE DAMAGE IN ALL DIRECTIONS AT A RATE OF 50 - 75 SF/GAL

MINIMUM 60 MILS OF POLYGUARD LM-95 APPLIED OVER THE DAMAGED AREA AND EXTENDED 1" BEYOND THE DAMAGE IN ALL DIRECTIONS OVER FABRIC PREPARED WITH POLYGUARD 650 LT LIQUID ADHESIVE OR POLYGUARD CALIFORNIA SEALANT AT A RATE OF 50 - 75 SF/GAL

POLYGUARD FABRIC TAPE APPLIED 6" IN ALL DIRECTIONS TO FABRIC SIDE OF POLYGUARD UNDERSLAB PREPARED WITH POLYGUARD 650 LT LIQUID ADHESIVE OR POLYGUARD CALIFORNIA SEALANT AT A RATE OF 50 - 75 SF/GAL AND CURED POLYGUARD LM-95



OVERVIEW @ REPAIR PATCH LESS THAN 2 INCHES

©POLYGUARD PRODUCTS, INC. MATERIAL SEPARATED FOR CLARITY